Division of Health Service Regulation (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING: 01 B. WING HAL045005 05/14/2015 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 720 ORR'S CAMP ROAD MCCULLOUGH'S REST HOME HENDERSONVILLE, NC 28739 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X50) TEACH DEFICIENCY MUST BE PRECEDED BY FULL EACH CORRECTIVE ACTION SHOULD BE PREFIX PRÉFIX REGULATORY OR LISC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) (C 000) (C 000) Initial Comments Report of Follow-up Survey by Dennis Harrell on 5-14-2015. CONSTRUCTION SECTION. Not all deficiencies were corrected. Further action is required. JUN 1 9 2015 (C 189) Building Equipment Maintained Safe, Operating (C 189) RECEIVED SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. Was rypeaced because therewere wires in (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: Based on observation, the battery powered emergency light in the left end of the corridor would not work when tested. Battery powered emergency lights that will not work properly for at least 90 minutes could endanger the residents and staff. Finding on 5-14-2015: A new battery had been purchased but the light had not been re-installed on the wall. all enrergence hart

Division of Health Service Regulation
AGORATCH DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Adm

(XXX) DATE

If con